

Cobalt

Cobalt and its oxides are also reduced, calcinated and stabilized in industrial furnaces. The following types of furnaces are in use:

- Conveyor belt reduction plant (Link Conveyor Belt Powder Reduction Plant),
- Pusher Type Sintering Furnaces (Link PTS),
- Rotary Drum Powder Reduction Furnaces (Link RDH)

Often the thermal heating plants in question are tailor made. Please feel free to approach us, and we will design a concept.

Foto Gallery





Contact:

CREMER Thermoprozessanlagen GmbH

Auf dem Flabig D-52355 Düren Germany

Tel.: +49 - 2421 - 968 30 0 Fax.: +49 - 2421 - 6 37 35

<u>info@cremer-ofenbau.de</u> <u>www.cremer-ofenbau.de</u>